TR77400 ECS SS12946







Reusable Solid Rocket Motor STS-113 Flight Readiness Review/CoFR

Motor Set RSRM-86

31 October 2002

Presented by Terry Boardman



ATK THIOKOL PROPULSION

P.O. Box 707, Brigham City, UT 84302-0707 (435) 863-3511







Agenda

Flight Readiness Review/CoFR

- 1.0 Previous Flight Assessment—STS-112
- 2.0 Certification Status—No Constraints
- 3.0 Changes Since Previous Flight—None
- 4.0 Configuration Inspection
 - 4.1 As-Built Versus As-Designed, Hardware, and Closeout Photo Review Status—No Issues
 - 4.2 Hardware Changeouts Since ET/SRB Mate Review—None
- 5.0 SMRB Nonconformances—None
- 6.0 Technical Issues/Special Topics
- 7.0 Readiness Assessment
- Backup LCC and Contingency Temperatures for STS-113









Previous Flight Assessment—STS-112

1.0-1

Disassembly Evaluation Summary—Status of Disassembly Activity

KSC Operations		LH RSRM	RH RSRM	Remarks				
Initial LH/RH SRB viewing	*	Complete	Complete					
SRB/RSRM walkaround assessment	*	Complete	Complete					
Demate/evaluate aft exit cone (AEC)	*	Complete	Complete					
Remove/evaluate S&A and OPTs	*	Complete	Complete					
Remove/evaluate nozzle	*	Complete	Complete					
Remove/evaluate stiffener rings/stubs		Complete	Complete					
Remove/evaluate igniter	*	Complete	Complete					
Demate/evaluate field joints/evaluate insulation	*	Complete	Complete					
Utah Operations								
Disassemble/evaluate nozzle (joint No. 4 and 5)	*	Complete	Complete					
Disassemble/evaluate nozzle (joint No. 2 and 3)	*	Complete	Complete					
Disassemble/evaluate S&A	*	Complete	Complete					
Washout nozzle phenolics		10 Jan 2003	10 Jan 2003					
Washout nozzle AEC phenolics		10 Jan 2003	10 Jan 2003					
Measure/evaluate aft dome insulation		28 Feb 2003	28 Feb 2003					
Measure/evaluate RH segment and igniter insulation		N/A	28 Feb 2003					

^{*} RSRM Project committed to complete prior to next launch

No constraints to STS-113 flight









Technical Issues/Special Topics

6.0 - 1

Special Topic—Missing Nozzle Nose Cap Radial X-ray Film

Observation

 During a 100-percent audit of STS-113 x-ray inspection film, it was noted that all RH nozzle nose cap phenolic component radial shots were missing

Concern

Evaluation of nose cap phenolic for critical flaws

Discussion

- Inspection of a nozzle nose cap includes a minimum of 720 tangent films and 66 radial films—all 720 STS-113 nose cap tangential shots accounted for and reevaluated with no defects noted
 - Tangent film shots provide 100-percent coverage of nose cap phenolic material for defects
- Immediate corrective action in place to assure all film is taken and read—long-term plan addresses x-ray planning and accounting systemic weaknesses

Flight Rationale

- Tangential film fully screens for critical nose cap defects—none noted
- STS-113 is safe to fly










Technical Issues/Special Topics

6.0-2

Special Topic—Missing Nozzle Nose Cap Radial X-ray Film (Cont)







ATK THIOKOL PROPULSION



STS-113 Readiness Assessment

Pending satisfactory completion of normal operations flow (per OMRSD), the RSRM hardware is ready to support flight for mission STS-113

31 October 2002

/s/ T. A. Boardman

T. A. Boardman RSRM Deputy & Chief Engineer Thiokol

/s/ H. L. Reed

H. L. Reed
Director
RSRM Operations & Flight Support
Thiokol



/s/ R. K. Burt

R. K. Burt Chief Engineer, RSRM Project NASA, MSFC

/s/ M. U. Rudolphi

M. U. Rudolphi Manager RSRM Project Office NASA, MSFC







Backup-1

Current Flight Predictions

LCC and Contingency Temperatures for STS-113

Heater Location	<u>LCC</u>	Minimum Allowable Sensor Temperature*	
		<u>LH</u>	<u>RH</u>
lgniter	74°F	72°F	72°F
Forward Field Joint	86°F	71°F	65°F
Center Field Joint	86°F	72°F	68°F
Aft Field Joint	86°F	73 ° F	68°F
Nozzle-to-Case Joint	75°F	63°F	63° F

*LCC contingency temperature in the event of heater failure Note: Calculation includes all standard repair conditions

